

# NEBO<sup>®</sup>

## EINSTEIN CAP<sup>™</sup> 100



### RECHARGEABLE

Use the included charging cable to recharge the unit. This unit uses four LEDs to indicate battery level.

### POWER INDICATOR

When product is in use, LEDs indicate the level of the battery from approximately 25% (single LED) to 100% (all 4 LED illuminated) in 25% increments.

### CHARGING INDICATOR

When plugged in to charge, the indicators will light to indicate battery status (per above), and the last lighted indicator will flash to indicate the battery is charging.

When plugged in and charging is complete, all indicators will light continuously.

### BATTERY

This unit is powered by a Li-Ion battery.



### OPERATION

Press & release power button to turn the unit off and on and cycle through light modes:

**High > Low > Green > Off**

When light is ON for 8 seconds or longer, the next button press will turn the unit off.

**Strobe:** Double-tap button, the next press within 8 seconds will revert to last used mode.

**Direct-to-Green:** From OFF, press and hold power button.

**Memory:** The last mode used (except STROBE) will be stored & operation of the sequence above resumed when unit is turned off and then back on.

### PRODUCT GUARANTEE



If you experience a problem, please do not return to your local store. Contact our Customer Service team at **800-255-6061** or [www.nebotools.com/contact](http://www.nebotools.com/contact)

For more information, detailed video instructions, and warranty registration, visit [NEBOTOOLS.com](http://NEBOTOOLS.com)